

FIRE REFURBISHING PROGRAM TESTIMONIAL

We received the bar yesterday and unpacked it today. It was in good shape and no damage was found. From start to finish – we had 2 hours with 2 people to complete the entire changeover of the bar. This time frame included removal of the old bar from the truck.

The instructions were exceptionally clear and having the two pictures was very helpful. We had to drill a couple of holes in the existing mounting blocks to accommodate the mounting bolts of the new bar.

The wiring box was a godsend. This made the job simple and insured it to be successful. We wired it up and it worked the first time out of the gate. Fit and finish were good.

Included in the shipment was a box of various hardware. We used the 8 nuts and bolts as well as male/female spade connectors that were in the box. The only thing we would recommend would be the addition of a few more male/female connectors, as the count on these were exact. There were sufficient butt connectors present for the wiring. We had two wires we did not use due to the bar configuration.

Overall, the time and effort at your end paid off. I believe you have a winner here. Appreciated the opportunity to help on this.

Thank-you,
Jim

Chief Jim Steele
Van Wert Fire Department
515 E. Main St.
Van Wert, OH 45891